

Reliability Test Record

Product Code:	(2026-27)P00163				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.10 mm, Weight/ pc: 0.0328 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 pcs	Sample No:	01
100 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				

Reliability Test Record

Product Code:	(2026-27)P00163				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.10 mm, Weight/ pc: 0.0328 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 pcs	Sample No:	02
100 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				

Reliability Test Record

Product Code:	(2026-27)P00163				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.10 mm, Weight/ pc: 0.0328 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 pcs	Sample No:	03
100 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:	HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT HT				
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			

Reliability Test Record

Product Code:	(2026-27)P00163				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.10 mm, Weight/ pc: 0.0328 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	04
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			



Reliability Test Record

✓ Product Code:	(2026-27)P00164				
✓ Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
✓ Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.12 mm, Weight/ pc: 0.0392 gm				
✓ Kt / Col:	9Kt/ Yellow.				
✓ Stamping Sign & Position:	9K @ 12'o Clock Position.				
✓ Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 pcs	Sample No:	01
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			

Reliability Test Record

Product Code:	(2026-27)P00164				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.12 mm, Weight/ pc: 0.0392 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles , applying the specified dead weights test after every 100 cycles . Holding Time Per Weight: 30-40 Sec .				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	02
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			

Reliability Test Record

Product Code:	(2026-27)P00164				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.12 mm, Weight/ pc: 0.0392 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles , applying the specified dead weights test after every 100 cycles . Holding Time Per Weight: 30-40 Sec .				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	03
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			

Department: Quality Assurance



Reliability Test Record

Product Code:	(2026-27)P00165				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.15 mm, Weight/ pc: 0.0495 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	01
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				



Reliability Test Record

Product Code:	(2026-27)P00165				
✓ Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
✓ Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.15 mm, Weight/ pc: 0.0495 gm				
✓ Kt / Col:	9Kt/ Yellow.				
✓ Stamping Sign & Position:	9K @ 12'o Clock Position.				
✓ Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	02
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm				
Holding Test with Dead Weight	15 gm				
Holding Test with Dead Weight	20 gm				

Reliability Test Record

Product Code:	(2026-27)P00165				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.15 mm, Weight/ pc: 0.0495 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles, applying the specified dead weights test after every 100 cycles. Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 pcs	Sample No:	03
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			

Reliability Test Record

Product Code:	(2026-27)P00165				
Surface Inspection:	Surface Scratches, Cracks, Porosity, Shape, Stamping Details, Silicon Outer Surface.				
Dimensional Inspection:	Width: 6.30 & Height: 5.00 mm, Thickness- 0.15 mm, Weight/ pc: 0.0495 gm				
Kt / Col:	9Kt/ Yellow.				
Stamping Sign & Position:	9K @ 12'o Clock Position.				
Functional Inspections:	On-Off Cycle Test for 300 cycles , applying the specified dead weights test after every 100 cycles . Holding Time Per Weight: 30-40 Sec.				
Sample Size:	20 Pcs.	Samples Checked:	04 PCS	Sample No:	04
100 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
200 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			
300 On-Off Cycles:					
Holding Test with Dead Weight	10 gm	✓			
Holding Test with Dead Weight	15 gm	✓			
Holding Test with Dead Weight	20 gm	✓			